Work Orde Monday, Septem										·		Page 1
Revision ID:	D412-702-30		,	Accept				s	etup			
	Harness Assen 9/27/2010 10/4/2010	Start Qty: 4.00 Req'd Qty: 4.00	138 1101 1001 188 1101 1801		Cust Item I Customer:	D:				Stop		
Approvals:	Process Pla	n:	Date: 10-9-37	Tooling: SPC (Y/N):		nte:		R	Run	Start Stop		
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr							<u></u> -			
DSI 9511	Α											
100 Small Fab				0.00				4	, Sio	/10	/18	(2)
Small Fab		Memo Assemble a	as per dwg ICA D412-702 p						/		•	
		QC5- Inspect part comp	oleteness to step on W/O	0.00				2				
QC . Quality Control		Memo		0.00								
												Λ

120

Packaging

Memo

0.00

0.00

Packaging

Identify with P/N & CHG# and pack for shipping as per PPP D412-702-307 CHG001
Location:
PPP Rev:

Miles of w

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date C	⊋ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
					·				Frod Wigi				
								İ					
Part No	:	PAR #:	Fault Ca	tegory:	NCI	NCR: Yes No DQA: Date:							
	Resolution:			ion:	QA	N/C Clo	sed:		Date: _				
NCR:			WORK OR	DER NON-CONFORM	ANCE	(NCR)							
DATE	STEP	Description of NC				tion B Verification			Approval	Approval			
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section (Chief Eng	QC Inspector			
							-						
										•-			
		+							,				

Work Order ID 62327

Monday, September 27, 2010 11:28:59 AM



Page 2

Item ID:

D412-702-307

Accept



Date:

Tool # Plan

Code

Setup Start



Revision ID:

Item Name:

Harness Assembly

Start Date:

9/27/2010

Start Qty: 4.00

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

A	D	D	ro	V	al	s:

Process Plan: _____

Operation

Description

Date:_____

Date: Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Tool ID

Run

Reject

Qty



Sequence ID/

Work Center ID

130

Required Date: 10/4/2010

QC Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Accept

Qty

Start Stop

Stop



Reject

Number

Insp.

Stamp

W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHA	NGE	By	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
-v	7,												
Part No	•	PAR #:	Fault Cate	gory.	NCR: Y	es N	n DQ	Δ.	Date:				
		esolution:											
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	ICR)							
DATE	STEP	Description of NC		tion B	VARIT			Approval	Approval				
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	• Secti	on C	Chief Eng	QC Inspector			
I													
					ŀ								
741								a.,					
rest the .							,						
				:									

Picklist Print

Monday, September 27, 2010 11:29:04 AM

Work Order ID: 62327

Parent Item:

D412-702-307

Parent Item Name: Harness Assembly



Start Date: 9/27/2010

Required Date: 10/4/2010

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP Rev: A new issue DD 10.04.30 verified:EC

Comments:	PP Rev:A new issi	ue DD 10.04.30	verified	1:EC									
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3573-3		Manufactured	No			100	Each	9.0000		431	10	/18	-
				Location	<u>1</u>	Loc (<u>Otv</u>	Loc Code					
				ST244			9		_				
,					50473		1		_		_		
					57223		1		_		_		
					59452		7		_	\prec	_		
14088-041 Marie Hall Hall Hall Hall Hall Hall Hall Hal		Manufactured	No			100	Each	5.0000		# 2 	<u> </u>	/18	
				<u>Locatio</u>	<u>n</u>	Loc	<u>Oty</u>	Loc Code			B62	2 2 3	(=
				ST272A			5		•		0000	$\sim \sim$	
					58232		1		_		_		
					61595		4		_		_		
MS24693-S272		Purchased	No			100	Each	137.0000	4	16	0/10	/18	·····
				Location	<u>n</u>	Loc (<u>Oty</u>	Loc Code					
				ST288			137				_		
					111548		i				_		
					112492		136		_	6	_		

Page 1

Dail AC	· ospace	- 										
DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng												
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	<i>,</i> [Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							ļ					
							·					
Part No	Part No: PAR #:		Fault Cate	gory:	_ NCR: Y	es No	DQA	:	_ Date: _			
	Resolution:		Disposition	1:	QA: N/0	C Close	ed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	ICR)						
		Description of NC		Corrective Action Sect	ion B		Vorific	ation	Approval Approv			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	iption Sign Date				Chief Eng	QC Inspector		
										İ		
			i									
							,					

Picklist Print

Monday, September 27, 2010 11:29:04 AM

Work Order ID: 62327

Parent Item:

D412-702-307

Parent Item Name: Harness Assembly



Start Date: 9/27/2010

Required Date: 10/4/2010

Page 2

Start Qty: 4.00

Required Qty: 4.00

AN960JD10LL

Washer

Purchased

Purchased

100

100

Each

4,335.000

Location ST349

No

No

19085 19600

4335 472 3863 Each

Loc Qty

Loc Qty

Loc Code

1,882.000

MS21042L3

Nut

Location


ST300


1882 114523 109 114784 1773

Loc Code

Dart Ae	rospace	: Ltd						•
W/O:			WO	RK ORDER CHANGE	ES			J
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•					
Part No		PAR #:	Fault Category: NCR: Yes				Date: _	
	Re	esolution:	Disposition	ı:	QA: N/C Cid	osed:	Date: _	
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCR)		
D.47F	0750	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector

ICA Page 79 (80 blank) of 98





DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

COPYRIGHT © 2004 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	Jopasi											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						·						
Part No	•	PAR #:	Fault Cate	adory.	NCR: Ves	No DO	Δ.	Date:				
Resolution:												
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)		· · ·				
DATE	STEP	Description of NC		on B	Verific	cation	Approval	Approval				
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector			
	<u>.</u>			a.								
	1					,		:				
ł	1				l			1	1			

[·] H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE